

FAQ

How to Adjust the Background of the Measurement Result Box

[FAQ – Measurement Results]


- Question
Can I make the background of the measurement result box transparent or opaque?

- Answer

■ Path: Setup > Measurement > Display

In **Show Result Background**, select **On** or **Off**.

- **On**: The background is opaque.
- **Off**: The background is transparent.



When **Off** is selected, the background becomes transparent.

- If the result box overlaps with the image, the underlying ultrasound image remains visible.